



# Pipeline Condition Assessment













# Technology – Leak Detection



# Technology – EM&Ultra










# Consequence of Failure





	# Pipes
Total Pipes	9628
Pipes with WB	31

Total Leaks	12






# Validation of Results







# Technology – Preventive Monitoring









# Technology – Preventive Monitoring





# What about Metallic pipes?





# Xylem – Assessment Services



**30**

Years of experience



**+500**

Engineers, scientists and technicians




**40**

Countries with References



**+25,000**

KM of pipe inspected





# Advanced Engineering Assessment

